

100/200/300/400


USB OUTPUT INTERFACE

- ◆ The cable without software, push the black button or footswitch, the data can be transferred into Excel, Word directly.
- ◆ The cable with software, the data can be transferred into the software at a set interval time automatically.




100-11

CABLE



Software




Code	Software	Plug to product	Products
100-03	Without		for digital calipers with following electronics
100-04	With		
100-03L	Without		for digital height gage with following electronics
100-04L	With		
100-11	Without		for digital calipers with following electronics
100-12	With		
100-15	Without		for digital calipers and height gage with following electronics
100-17	Without		for digital calipers with following electronics
200-03	Without		for digital indicators with following electronics
200-04	With		

Code	Software	Plug to product	Products
200-01	Without		for digital indicators with following electronics
200-02	With		
300-03	Without		for digital micrometers with data output with following electronics
300-04	With		
300-51	Without		for digital micrometers with data output with following electronics

* NEW

Connect foot switch to transfer the data (code: 400-01)



Code	Name
400-01	footswitch

* Confirm the electronics output port type when placing orders