




# TAPER INSPECTION INSTRUMENT



- Check the taper angle of taper bar / taper plug gauges / Morse taper / ISO taper etc. The run out can be checked as well
- Sine bar accuracy ( $\alpha=30^\circ$ ):  $\pm 5$  seconds



**4157-200**



| Code     | Center height (H) | Center distance (L) |
|----------|-------------------|---------------------|
| 4157-200 | 65mm              | 200mm               |