



PER FRESE WELDON - END MILL HOLDERS - HSK63A

Cod.	TYPE	H	G6.3/15000	
			AT2	WE
HSK.A.63.65.WE6	HSK63A H65 WE6	65	25	6
HSK.A.63.100.WE6	HSK63A H100 WE6	100	25	6
HSK.A.63.160.WE6	HSK63A H160 WE6	160	25	6
HSK.A.63.65.WE8	HSK63A H65 WE8	65	28	8
HSK.A.63.100.WE8	HSK63A H100 WE8	100	28	8
HSK.A.63.160.WE8	HSK63A H160 WE8	160	28	8
HSK.A.63.65.WE10	HSK63A H65 WE10	65	35	10
HSK.A.63.100.WE10	HSK63A H100 WE10	100	35	10
HSK.A.63.160.WE10	HSK63A H160 WE10	160	35	10
HSK.A.63.80.WE12	HSK63A H80 WE12	80	42	12
HSK.A.63.100.WE12	HSK63A H100 WE12	100	42	12
HSK.A.63.160.WE12	HSK63A H160 WE12	160	42	12
HSK.A.63.80.WE14	HSK63A H80 WE14	80	44	14
HSK.A.63.100.WE14	HSK63A H100 WE14	100	44	14
HSK.A.63.160.WE14	HSK63A H160 WE14	160	44	14
HSK.A.63.80.WE16	HSK63A H80 WE16	80	48	16
HSK.A.63.100.WE16	HSK63A H100 WE16	100	48	16
HSK.A.63.160.WE16	HSK63A H160 WE16	160	48	16
HSK.A.63.80.WE18	HSK63A H80 WE18	80	48	18
HSK.A.63.100.WE18	HSK63A H100 WE18	100	48	18
HSK.A.63.160.WE18	HSK63A H160 WE18	160	48	18
HSK.A.63.80.WE20	HSK63A H80 WE20	80	52	20
HSK.A.63.100.WE20	HSK63A H100 WE20	100	52	20
HSK.A.63.160.WE20	HSK63A H160 WE20	160	52	20
HSK.A.63.110.WE25	HSK63A H110 WE25	110	65	25
HSK.A.63.160.WE25	HSK63A H160 WE25	160	65	25
HSK.A.63.110.WE32	HSK63A H110 WE32	110	72	32
HSK.A.63.160.WE32	HSK63A H160 WE32	160	72	32



PER FRESE WELDON - END MILL HOLDERS - HSK80A

Cod.	TYPE	H	G6.3/15000	
			AT2	WE
HSK.A.80.80.WE6	HSK80A H80 WE6	80	25	6
HSK.A.80.80.WE8	HSK80A H80 WE8	80	28	8
HSK.A.80.80.WE10	HSK80A H80 WE10	80	35	10
HSK.A.80.80.WE12	HSK80A H80 WE12	80	42	12
HSK.A.80.80.WE14	HSK80A H80 WE14	80	44	14
HSK.A.80.100.WE16	HSK80A H100 WE16	100	48	16
HSK.A.80.100.WE18	HSK80A H100 WE18	100	50	18
HSK.A.80.100.WE20	HSK80A H100 WE20	100	52	20
HSK.A.80.100.WE25	HSK80A H100 WE25	100	65	25
HSK.A.80.110.WE32	HSK80A H110 WE32	110	72	32



PER FRESE WELDON - END MILL HOLDERS - HSK100A

Cod.	TYPE	H	G6.3/15000	
			AT2	WE
HSK.A.100.80.WE6	HSK100A H80 WE6	80	25	6
HSK.A.100.80.WE8	HSK100A H80 WE8	80	28	8
HSK.A.100.80.WE10	HSK100A H80 WE10	80	35	10
HSK.A.100.100.WE12	HSK100A H100 WE12	100	42	12
HSK.A.100.100.WE14	HSK100A H100 WE14	100	44	14
HSK.A.100.100.WE16	HSK100A H100 WE16	100	48	16
HSK.A.100.100.WE18	HSK100A H100 WE18	100	50	18
HSK.A.100.100.WE20	HSK100A H100 WE20	100	52	20
HSK.A.100.100.WE25	HSK100A H100 WE25	100	65	25
HSK.A.100.100.WE32	HSK100A H100 WE32	100	72	32
HSK.A.100.105.WE40	HSK100A H105 WE40	100	80	40