


COUNTING SCALES

- LCD display, with backlight
- Zero-setting, subtracting tare value, counting, accumulation, checking alarm
- Overload alarm

DATA
OUTPUT



printer (optional)



8101-30

SPECIFICATION

Code	Maximum capacity	Minimum capacity	Division	Verification interval	Output	Operating temperature	Power	Dimensions of pan
8101-6	6kg	4g	0.2g	2g	no	-10~40℃	rechargeable battery(6V/3.2Ah) power adapter (12V/500mA)	263×204mm
8101-15	15kg	10g	0.5g	5g				
8101-30	30kg	20g	1g	10g				
8101-6D	6kg	4g	0.2g	2g	RS232			
8101-15D	15kg	10g	0.5g	5g				
8101-30D	30kg	20g	1g	10g				

OPTIONAL ACCESSORY (for scales with RS232 only)

Printer	8001-PRINTER
---------	--------------