






489

SURFACE PROFILE GAUGE

- ◆ Measure peak-to-valley height of blast cleaned surface.
If the profile is too low, the adhesion of the coating to the surface will be reduced.
If the profile is too high, it is dangerous that the profile peaks will remain non-coating, rust spots maybe occur.
- ◆ Meet ASTM D4417-B
- ◆ Zero set block is included, set zero before measurement
- ◆ Stainless steel base

measure peak-to-valley height
of blast cleaned surface



Code	Range	Dial indicator stroke	Dial indicator graduation	Accuracy
489-001-01	0-1mm	1mm	0.001mm	±0.005mm